MARMON/KEYSTONE LLC

THE PIPE AND TUBING PEOPLE

P.O. BOX 992, Butler, PA 16003-0992 EMERGENCY PHONE NUMBER (724) 283-3000

ISSUE DATE
JANUARY 1, 2015

MATERIAL SAFETY DATA SHEET

TRADE NAME (Common Name or Synonym)

Carbon and Alloy Steels

CHEMICAL NAME

AISI/SAE Grades 10xx thru 93xx

I. INGREDIENTS

Material or Component	CAS Number	% Weight	EXPOSURE LIMITS		
			OSHA PEL (mg/m ³)	ACGIH TLV (mg/m³)	
Base Metai					
Iron (Fe)	1309-37-1	86.5-99-5	10 Oxide Fume	5 Oxide Fume	
Alloying Elements					
Aluminum (AI)	7429-90-5	<0.1-0.5	15 Dust	10 Dust/5 Fume	
Bismuth (BI)	7440-69-9	<0.2-0.5	Not Established	Not Established	
Boron (B)	7440-42-8	<.01-1.0	15 Oxide Fume	10 Oxide Fume	
Carbon (C)	7440-44-0	<.10-1.5	Not Established	3.5 AS Carbon Black	
Chromium (Cr)	7440-47-3	<.40-10	1.0 Chrome Metal	0.5 Chrome Metal	
Columbium (Cb)	7440-03-1	<.1535	Not Established	Not Established	
Copper (Cu)	7440-50-8	<.30-1.90	1.0 Furne/1.0 Dust	O.2 Fume/1.0 Dust	
Lead (Pb)	7439-92-1	<.0115	.05 Dust & Fume	.15 Dust & Fume	
Manganese (Mn)	7439-96-5	<.04-0.7	5c Dust/5c Fume	5c Dust/1 Furne	
Molybdenum (Mo)	7439-98-7	<.15-1.10	15 Insoluble Compounds	10 Insoluble Compounds	
Nickel (Ni)	7440-02-0	<.01-10	1 Nickel Metal	1 Nickel Metal	
Phosphorous (P)	7723-14-0	<.04012	0.1 Phosphorous	O.1 Phosphorous	
Silicon (Si)	7440-21-3	<.15-2.00	15 Dust	10 Total Dust	
Sulfur (S)	7704-34-9	<.050-,35	13 Sulfur Dioxide	5 Sulfur Dioxide	
Vanadium (V)	7440-62-2	<.01-0.15	0.5c Dust/0.1c Fume	0.05 Dust/0.05 Fume	
Zinc Coating	1314-13-2	2 oz/ft ²	5 Oxide Fume	10 Dust/5 Fume	
Aluminum Coating	7429-90-5	0.5 oz/ft ²	Not Established	10 Dust/5 Fume	

Note: The above listing is a summary of elements used in alloying steel. Various grades of steel will contain different combinations of these elements. Trace elements may also be present in minute amounts. No permissible exposure limits (PEL) or thresholds limit values (TLV) exist for steel. Values shown are applicable to component elements.

II. PHYSICAL DATA

MATERIAL IS (At N	ormal Conditions) D	E AND ODOR , Odorless	% VOLATILE BY VOLUME N/A	VAPOR DENSITY N/A
ACIDITY/ALKALINITY pH=N/A	Melting Point Approx Boiling Point	Specific G Solubility	Fravity (H ₂ 0) = 1) Approx. 7 in water (% by weight) N/	VAPOR PRESSURE (mm Hg at 20° C) N/A

III. PERSONAL PROTECTIVE EQUIPMENT

RESPIRATORY PROTECTION Appropriate dust/mist/fume respirator
should be used to avoid excessive inhalation of particulates. If
exposure limits are reached or exceeded, use NIOSH approved
equipment.

HANDS, ARMS AND BODY Protective gloves should be worn as required for welding, burning or handling operations.

EYES AND FACE Safety glasses should be worn when grinding or cutting. Face shields should be worn when welding or cutting.

OTHER CLOTHING AND EQUIPMENT As required depending on operations and safety codes.

IV. EMERGENCY MEDICAL PROCEDURES

INHALATION: EYE CONTACT: SKIN CONTACT: INGESTION: Remove to fresh air; if condition continues, consult a physician.

Flush thoroughly with running water to remove particulate; obtain medical attention.

Remove particles by washing thoroughly with soap and water. Seek medical attention if condition persists.

If significant amounts of metal are ingested, consult physician.

V. HEALTH/SAFETY INFORMATION

Steel products in their solid state present no inhalation, ingestion, or contact health hazard. Operations such as burning, welding, sawing, brazing, grinding, and machining, which result in elevating the temperature of the product to, or above its melting point, or result in the generation of airborne particulates may present hazards. The major exposure hazard is inhalation. Effects or overexposure to fume and dust are as follows: ACUTE: Excessive inhalation of metallic fumes and dust may result in irritation of eyes, nose and throat. High concentrations of fumes and dust of iron-oxide, manganese, copper, zine and lead may result in metal fume fever. Typical symptoms last from 12 to 48 hours and consist of a metallic taste in the mouth, dryness and irritation of the throat, chills and fever. CHRONIC: Chronic and prolonged inhalation of high concentrations of fumes or dust of the following elements may lead to the conditions listed opposite the element: Aluminum: May initiate fibrotic changes to lung tissue Bismuth: No chronic debilitating symptoms indicated Boron: No chronic debilitating symptoms indicated Chromium: Lesions of the skin and mucous membranes, possibly cancer of the nose or lungs-bronchogenic carcinoma Health Copper: No chronic debilitating symptoms indicated Iron: Siderosis, pulmonary effects. No chronic debilitating symptoms indicated Lead: Anemia, urinary dysfunction, weakness, constipation, nausea, nervous disorder Manganese: Bronchitis, pneumonitis, lack of coordination Molybdenum: Respiratory tract irritation, possible liver and kidney damage, bone deformity Nickel: Lesions of the skin and mucous membrenes, possibly cancer of the nose or lungs-bronchogenic carcinoma Phosphorous: Necrosis of the mandible Sulfur: (As sulfur dioxide) Edema of the lungs Vanadium: (As vanadium pentoxide) Emphysema, pneumonia Zinc: Gastronintestinal inflammation reported in animal studies MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: Individuals with chronic respiratory disorders (i.e.: asthma, chronic bronchitis, emphysema, etc.) may be adversely affected by any fume or airborne particulate matter exposure. OCCUPATIONAL EXPOSURE LIMITS: See Products Ingradients Section I. Chromium and Nickel have been identified by the International Agency for Research on Cancer (IARC) and/or the National Toxicology Program (NTP) as potential cancer causing agents. FLAMMABLE LIMITS IN AIR **AUTO IGNITION TEMPERATURE** EXTINGUISHING MEDIA FLASH POINT For molten metal use dry power or sand. Lower Explosion Fire and Upper ° F N/A N/A EXTINGUISHING MEDIA NOT TO BE USED FIRE AND EXPLOSION HAZARDS Steel tubular products do not present fire or explosion hexards under normal Do not use water on molten metal. conditions. Fine metal particles such as produced in grinding or sawing can burn. High concentrations of metallic fines in the air may present an explosion hazard. INCOMPATIBILITY (MATERIALS TO AVOID) STABILITY Reacts with strong soids to form hydrogen gas. Reactivity CONDITIONS TO AVOID: Steel at temperatures above the melting point may liberate fume containing oxides of iron and alloying elements. Avoid generation of airborne fume and dust. Metallic dust or fumes may be produced during welding, burning, grinding and possibly machining. Refer to ANSI Z49.1.

VI. ENVIRONMENTAL

SPILL OR LEAK PROCEDURES

Fine turnings and small chips should be swept or vacuumed. Scrap metal can be reclaimed for re-use.

WASTE DISPOSAL METHOD*

Used or unused product should be disposed of in accordance with Federal, State or Local Laws and Regulations. Disposer must comply with Federal, State and Local disposal or discharge laws.

VII. ADDITIONAL INFORMATION

In welding, precautions should be taken for airborne contaminants which may originate from components of the welding rod. Arc or spark generated when welding or burning could be a source of ignition for combustion and flammable materials.

DISCLAIMER

The information in this MSDS was obtained from sources which we believe are reliable, however, the information is provided without any representation or warranty, express or implied, regarding the accuracy or correctness.

The conditions or methods of handling, storage, use and disposal of the product are beyond our control and may be be beyond our knowledge. For this and other reasons, we do not assume responsibility and expressly disclaim liability for loss, damage or expense arising out of or in any way connected with the handling, storage, use or disposal of the product.